

Spare Parts List



Label Printer

MACH 4S

for the following products

Family	Type	
MACH 4S	-	MACH 4.3S/200B
	-	MACH 4.3S/200P
	-	MACH 4.3S/200C
	MACH 4S/300B	MACH 4.3S/300B
	MACH 4S/300P	MACH 4.3S/300P
	MACH 4S/300C	MACH 4.3S/300C
	MACH 4S/600B	-
	MACH 4S/600P	-
	MACH 4S/600C	-

Table of Contents

1	Main Assemblies	3
2	Print Assembly	4
3	Transport Assembly	5
4	Control Panel	6
5	Spare Parts Register	7
6	Packaging/Accessories	9

Edition: 01/2021 - Part No. 9003100

Copyright

This documentation as well as translation hereof are property of cab Produkttechnik GmbH & Co. KG.

The replication, conversion, duplication or divulgement of the whole manual or parts of it for other intentions than its original intended purpose - in particular the procurement of spare parts for products sold by cab – demand the previous written authorization by cab.

Editor

Regarding questions or comments please contact cab Produkttechnik GmbH & Co. KG.

Topicality

Due to the constant further development of our products discrepancies between documentation and product can occur.

Please check www.cab.de for the latest update.

Terms and conditions

Deliveries and performances are effected under the "General conditions of sale of cab"

Germany
cab Produkttechnik GmbH & Co KG
 Karlsruhe
 Phone +49 721 6626 0
www.cab.de

USA
cab Technology, Inc.
 Chelmsford, MA
 Phone +1 978 250 8321
www.cab.de/us

Taiwan
cab Technology Co., Ltd.
 Taipei
 Phone +886 (02) 8227 3966
www.cab.de/tw

China
cab (Shanghai) Trading Co., Ltd.
 Guangzhou
 Phone +86 (020) 2831 7358
www.cab.de/cn

France
cab Technologies S.à.r.l.
 Niedermörsen
 Phone +33 388 722501
www.cab.de/fr

Mexico
cab Technology, Inc.
 Juárez
 Phone +52 656 682 4301
www.cab.de/es


China
cab (Shanghai) Trading Co., Ltd.
 Shanghai
 Phone +86 (021) 6236 3161
www.cab.de/cn

South Africa
cab Technology (Pty) Ltd.
 Randburg
 Phone +27 11 886 3580
www.cab.de/za

No	Part No.	Description	PU	Note	Serial No.	
					from	to
1	5984648.001	Roll Retainer	1			
2	5984299.001	Roll Retainer	1			
3	5540690.002	Adapter	1			
4	5984298.001	Margin Stop	1			
5	5984297.001	Cover	1			
6	5902414.001	Screw EJOT-PT-K30x12	10			
7	5984296.001	Covering Hood	1			
8	5902592.001	Screw DIN7984-M4x10	10			
9	5551353.001	PCB CPU X4.2	1			
10	5977326.001	Cable Power Supply	1			
11	5551162.001	Power Supply	1			
12	5540617.001	Foot	5			
13	5984607.001	Base Tub	1			


No	Part No.	Description	PU	Note	Serial No.	
					from	to
14	5984700.001	Ventilator	1			
15	5984647.001	Ribbon Core	1			
16	5984615.001	Print Module	1			
17	5902007.001	Screw DIN912-M3x6	10			
18	5984668.001	Plate	1			
19.1	5977444.001	Printhead 4/300	1	4/300		
19.2	5977380.001	Printhead 4/600	1	4/600		
19.3	5977382.001	Printhead 4.3/200	1	4.3/200		
19.4	5977383.001	Printhead 4.3/300	1	4.3/300		
20	5984649.001	Drive Roller	1			
21.1	5984642.001	Control Panel B	1	B		
21.2	5984643.001	Control Panel P	1	P		
21.3	5984644.001	Control Panel C	1	C		

Notes	B	MACH xS/...B
	C	MACH xS/...C
	P	MACH xS/...P
	1	MACH 4S/300x
	2	MACH 4S/600x
	3	MACH 4.3S/200x
	4	MACH 4.3S/300x



No	Part No.	Description	PU	Note	Serial No.	
					from	to
6	5902414.001	Screw EJOT-PT-K30x12	10			
22	5984666.001	Swing	1			
23	5955074.001	Roller	10			
24	5540641.001	Axle	1			
25	5540606.002	Swing Arm	1			
26	5903525.001	E-Ring DIN 6799-4	10			
27	5540687.001	Spring	1			
28	5540654.001	Axle	1			
29	5540688.001	Spring	1			
30	5540681.002	Cover	1			
31	5905093.001	Spring	10			
32	5540607.001	Unlocking Device	1			
33	5902940.001	Screw DIN912-M3x18	10			
34	5977481.001	Pivot Arm	1			
35	5906136.001	Spring	5			
36	5541081.001	Antistatic Brush	1			
37	5540891.001	Attachment Wheel	1			
38	5540941.002	Frame	1			
39	5540890.001	Tensioning Wheel	1			
40	5540648.001	Washer	5			
41	5540649.001	Friction Disc	5			
42	5540646.001	Washer	5			


No	Part No.	Description	PU	Note	Serial No.	
					from	to
43	5540701.001	Ribbon Sensor Wheel	1			
44	5906132.001	Spring	10			
45	5540703.001	Holder	1			
46	5984614.001	Locking Washer	1			
47	5906143.001	Spring	10			
48	5541078.001	Washer	5			
49	5540978.001	Slipping Clutch	1			
50	5540613.001	Gear Wheel Z30	1			
51	5540949.001	Unlocking	1			
52	5984613.001	Axle	1			
53	5540682.002	Cover	1			
54	5540630.001	Set Screw	1			
55	5903507.001	E-Ring DIN6799-3.2	10			
56	5540629.001	Holder	1			
57	5905019.001	Spring	10			
58	5984604.001	Printhead Holder	1			
59	5540898.001	PCB See-through Sender	1			
60	5984693.001	Cable Printhead	1			
61	5906209.001	Ferrite	1			
62	5984612.001	Frame Module	1			
63	5902817.001	Screw sim. ISO7380-M4x6	10			



No	Part No.	Description	PU	Note	Serial No.	
					from	to
6	5902414.001	Screw EJOT-PT-K30x12	10			
26	5903525.001	E-Ring DIN 6799-4	10			
50	5540613.001	Gear Wheel Z30	1			
60	5984693.001	Cable Printhead	1			
64	5906125.001	Damper	1			
65	5984611.001	Stepper Motor	1			
66	5984691.001	Cable Sensors	1			
67	5984692.001	Cable Control Panel	1			
68	5551402.001	PCB Ribbon Sensor	1			
69	5984689.001	Cable Reflex Sensor	1			
70	5984690.001	Cable See-through Receiver	1			
71	5984667.001	Chassis	1			
72	5540631.002	Set Wheel	1			
73	5540624.001	Gear Wheel Z38	1			

No	Part No.	Description	PU	Note	Serial No.	
					from	to
74	5540615.001	Gear Wheel Z26	1			
75	5903528.001	Snap Ring G5	10			
76	5540628.001	Threaded Rod	1			
77	5540684.002	Guide	1			
78	5540683.002	Gear Rack	1			
79	5540626.002	Gear Rack	1			
80	5540660.001	Gear Wheel Z14	1			
81	5984699.001	PCB Coupling	1			
82	5540869.001	PCB Reflex Sensor	1			
83	5955040.001	PCB See-through Receiver	1			
84	5540940.001	Cover Plate	1			
85	5984610.001	Transport Module	1			
86	5540666.001	Peel-off Edge	1	BP		


Bem.	B	MACH xS/...B
	P	MACH xS/...P



No	Part No.	Description	PU	Note	Serial No.	
					from	to
6	5902414.001	Screw EJOT-PT-K30x12	10			
21.1	5984642.001	Control Panel B	1	B		
21.2	5984643.001	Control Panel P	1	P		
21.3	5984644.001	Control Panel C	1	C		
87	5984664.001	Front Bezel	1			
88	5984688.001	Cable Display	1			
89	5984645.001	Display	1			
90	5984603.001	Cover	1			
91	5541208.002	Cover	1	BP		
92	5984685.001	PCB Present Sensor	1	P		
93	5984686.001	Cable Present Sensor	1	P		
94	5540669.001	Transport Locking Roller	1	P		
95	5540668.001	Axle	1	P		
96	5540672.001	Spring Guide	1	P		
97	5906168.001	Spring	10	P		
98	5984646.001	Dispense Module	1	P		
99	5984687.001	Cable Cutter	1	C		
100	5954132.001	Strip	5	C		
101	5984658.001	Drive	1	C		

No	Part No.	Description	PU	Note	Serial No.	
					from	to
102	5955015.001	Switch	1	C		
103	5541115.001	Clock Wheel	1	C		
104	5984654.001	Shaft	1	C		
105	5902144.001	Screw DIN7984-M3x5	10	C		
106	5903004.001	Washer DIN125-A3.2	10	C		
107	5902505.001	Nut DIN934-M3	10	C		
108	5541113.001	Lower Blade	1	C		
109	5541174.001	Spring	1	C		
110	5984673.001	Clamp	1	C		
111	5541118.001	Eccentric	1	C		
112	5541116.001	Screw	1	C		
113	5541119.001	Conrod	1	C		
114	5541120.001	Bushing	1	C		
115	5984651.001	Base Plate	1	C		
116	5902072.001	Screw DIN7985-M2x8	10	C		
117	5902873.001	Screw DIN7991-M3x6	10	C		
118	5541112.001	Upper Blade	1	C		
119	5541114.001	Paper Guide	1	C		
120	5984650.001	Cutter Module	1	C		

Notes	B	MACH xS/...B
	C	MACH xS/...C
	P	MACH xS/...P



5 Spare Parts Register

7

Pos.	Figure/Page				No.	Part No.	Description	PU	SPR					Notes	Serial No.	
															from	to
1		4			25	5540606.002	Swing Arm	1	-	-	-	-				
2		4			32	5540607.001	Unlocking Device	1	-	-	-	D				
3		4	5		50	5540613.001	Gear Wheel Z30	1	-	-	-	D				
4			5		74	5540615.001	Gear Wheel Z26	1	-	-	-	D				
5	3				12	5540617.001	Foot	5	-	-	-	C D				
6			5		73	5540624.001	Gear Wheel Z38	1	-	-	-	-				
7			5		79	5540626.002	Gear Rack	1	-	-	-	D				
8			5		76	5540628.001	Threaded Rod	1	-	-	-	-				
9		4			56	5540629.001	Holder	1	-	-	-	-				
10		4			54	5540630.001	Set Screw	1	-	-	-	-				
11			5		72	5540631.002	Set Wheel	1	-	-	-	-				
12		4			24	5540641.001	Axle	1	-	-	-	-				
13		4			42	5540646.001	Washer	5	-	-	-	D				
14		4			40	5540648.001	Washer	5	-	-	-	D				
15		4			41	5540649.001	Friction Disc	5	-	-	-	D				
16		4			28	5540654.001	Axle	1	-	-	-	-				
17			5		80	5540660.001	Gear Wheel Z14	1	-	-	-	-				
18			5		86	5540666.001	Peel-off Edge	1	-	-	-	C D	BP			
19				6	95	5540668.001	Axle	1	-	-	-	-	P			
20				6	94	5540669.001	Transport Locking Roller	1	-	-	-	D	P			
21				6	96	5540672.001	Spring Guide	1	-	-	-	-	P			
22		4			30	5540681.002	Cover	1	-	-	-	-				
23		4			53	5540682.002	Cover	1	-	-	-	-				
24			5		78	5540683.002	Gear Rack	1	-	-	-	-				
25			5		77	5540684.002	Guide	1	-	-	-	-				
26		4			27	5540687.001	Spring	1	-	-	-	-				
27		4			29	5540688.001	Spring	1	-	-	-	-				
28	3				3	5540690.002	Adapter	1	-	-	-	-				
29		4			43	5540701.001	Ribbon Sensor Wheel	1	-	-	-	-				
30		4			45	5540703.001	Holder	1	-	-	-	-				
31			5		82	5540869.001	PCB Reflex Sensor	1	-	-	-	C D				
32		4			39	5540890.001	Tensioning Wheel	1	-	-	-	D				
33		4			37	5540891.001	Attachment Wheel	1	-	-	-	D				
34		4			59	5540898.001	PCB See-through Sender	1	-	-	-	C D				
35			5		84	5540940.001	Cover Plate	1	-	-	-	-				
36		4			38	5540941.002	Frame	1	-	-	-	-				
37		4			51	5540949.001	Unlocking	1	-	-	-	-				
38		4			49	5540978.001	Slipping Clutch	1	-	-	-	C D				
39		4			48	5541078.001	Washer	5	-	-	-	-				
40		4			36	5541081.001	Antistatic Brush	1	-	-	-	-				
41				6	118	5541112.001	Upper Blade	1	A	B	C	D	C			
42				6	108	5541113.001	Lower Blade	1	A	B	C	D	C			
43				6	119	5541114.001	Paper Guide	1	-	-	-	D	C			
44				6	103	5541115.001	Clock Wheel	1	-	-	-	D	C			
45				6	112	5541116.001	Screw	1	-	-	-	-	C			
46				6	111	5541118.001	Eccentric	1	-	-	-	D	C			
47				6	113	5541119.001	Conrod	1	-	-	-	D	C			
48				6	114	5541120.001	Bushing	1	-	-	-	D	C			
49				6	109	5541174.001	Spring	1	-	-	-	C D	C			
50				6	91	5541208.002	Cover	1	-	-	-	-	BP			
51	3				11	5551162.001	Power Supply	1	-	-	-	C D				
52	3				9	5551353.001	PCB CPU X4.2	1	-	-	-	C D				
53			5		68	5551402.001	PCB Ribbon Sensor	1	-	-	-	C D				
54	3				17	5902007.001	Screw DIN912-M3x6	10	-	-	-	-				
55				6	116	5902072.001	Screw DIN7985-M2x8	10	-	-	-	-	C			
56				6	105	5902144.001	Screw DIN7984-M3x5	10	-	-	-	-	C			
57	3	4	5	6	6	5902414.001	Screw EJOT-PT-K30x12	10	-	-	-	-				
58				6	107	5902505.001	Nut DIN934-M3	10	-	-	-	-	C			
59	3				8	5902592.001	Screw DIN7984-M4x10	10	-	-	-	-				
60		4			63	5902817.001	Screw sim. ISO7380-M4x6	10	-	-	-	-				
61				6	117	5902873.001	Screw DIN7991-M3x6	10	-	-	-	-	C			
62		4			33	5902940.001	Screw DIN912-M3x18	10	-	-	-	-				

PU Package unit

Notes

B MACH xS/...B

C MACH xS/...C

P MACH xS/...P

1 MACH 4S/300x

2 MACH 4S/600x

3 MACH 4.3S/200x

4 MACH 4.3S/300x

SPR Recommendation

A - wearing parts and accessories

B - recommended spare parts for quick repair

C - recommended spare parts for distributors

D - recommended spare parts for central stores

Pos.	Figure/Page				No.	Part No.	Description	PU	SPR					Notes	Serial No.	
															from	to
63				6	106	5903004.001	Washer DIN125-A3.2	10	-	-	-	-	-	C		
64		4			55	5903507.001	E-Ring DIN6799-3.2	10	-	-	-	-	-			
65		4	5		26	5903525.001	E-Ring DIN 6799-4	10	-	-	-	-	-			
66			5		75	5903528.001	Snap Ring G5	10	-	-	-	-	-			
67		4			57	5905019.001	Spring	10	-	-	-	-	-			
68		4			31	5905093.001	Spring	10	-	-	-	C	D			
69			5		64	5906125.001	Damper	1	-	-	-	C	D			
70		4			44	5906132.001	Spring	10	-	-	-	-	-			
71		4			35	5906136.001	Spring	5	-	-	-	-	-			
72		4			47	5906143.001	Spring	10	-	-	-	-	-			
73				6	97	5906168.001	Spring	10	-	-	-	-	-	P		
74		4			61	5906209.001	Ferrite	1	-	-	-	-	-			
75				6	100	5954132.001	Strip	5	-	-	-	-	-	C		
76				6	102	5955015.001	Switch	1	-	-	-	C	D	C		
77			5		83	5955040.001	PCB See-through Receiver	1	-	-	-	C	D			
78		4			23	5955074.001	Roller	10	-	-	-	-	D			
79	3				10	5977326.001	Cable Power Supply	1	-	-	-	-	-			
80	3				19.2	5977380.001	Printhead 4/600	1	A	B	C	D	4/600			
81	3				19.3	5977382.001	Printhead 4.3/200	1	A	B	C	D	4.3/200			
82	3				19.4	5977383.001	Printhead 4.3/300	1	A	B	C	D	4.3/300			
83	3				19.1	5977444.001	Printhead 4/300	1	A	B	C	D	4/300			
84		4			34	5977481.001	Pivot Arm	1	-	-	-	-	-			
85	3				7	5984296.001	Covering Hood	1	-	-	-	-	-			
86	3				5	5984297.001	Cover	1	-	B	C	D				
87	3				4	5984298.001	Margin Stop	1	-	-	-	C	D			
88	3				2	5984299.001	Roll Retainer	1	-	-	-	C	D			
89				6	90	5984603.001	Cover	1	-	-	-	-	-			
90		4			58	5984604.001	Printhead Holder	1	-	-	-	-	-			
91	3				13	5984607.001	Base Tub	1	-	-	-	-	-			
92			5		85	5984610.001	Transport Module	1	-	-	-	C	D			
93			5		65	5984611.001	Stepper Motor	1	-	-	-	C	D			
94		4			62	5984612.001	Frame Module	1	-	-	-	-	-			
95		4			52	5984613.001	Axle	1	-	-	-	-	-			
96		4			46	5984614.001	Locking Washer	1	-	-	-	-	-			
97	3				16	5984615.001	Print Module	1	-	B	-	-	-			
98	3			6	21.1	5984642.001	Control Panel B	1	-	B	C	D	B			
99	3			6	21.2	5984643.001	Control Panel P	1	-	B	C	D	P			
100	3			6	21.3	5984644.001	Control Panel C	1	-	B	C	D	C			
101				6	89	5984645.001	Display	1	-	-	-	C	D			
102				6	98	5984646.001	Dispense Module	1	-	-	-	C	D	P		
103	3				15	5984647.001	Ribbon Core	1	A	B	C	D				
104	3				1	5984648.001	Roll Retainer	1	A	B	C	D				
105	3				20	5984649.001	Drive Roller	1	A	B	C	D				
106				6	120	5984650.001	Cutter Module	1	-	-	-	C	D	C		
107				6	115	5984651.001	Base Plate	1	-	-	-	-	-	C		
108				6	104	5984654.001	Shaft	1	-	-	-	-	-	C		
109				6	101	5984658.001	Drive	1	-	-	-	-	-	C		
110				6	87	5984664.001	Front Bezel	1	-	-	-	C	D			
111		4			22	5984666.001	Swing	1	-	-	-	-	-			
112			5		71	5984667.001	Chassis	1	-	-	-	-	-			
113	3				18	5984668.001	Plate	1	-	-	-	-	-			
114				6	110	5984673.001	Clamp	1	-	-	-	-	-	C		
115				6	92	5984685.001	PCB Present Sensor	1	-	-	-	C	D	P		
116				6	93	5984686.001	Cable Present Sensor	1	-	-	-	-	-	P		
117				6	99	5984687.001	Cable Cutter	1	-	-	-	-	-	C		
118				6	88	5984688.001	Cable Display	1	-	-	-	-	-			
119			5		69	5984689.001	Cable Reflex Sensor	1	-	-	-	-	-			
120			5		70	5984690.001	Cable See-through Receiver	1	-	-	-	-	-			
121			5		66	5984691.001	Cable Sensors	1	-	-	-	C	D			
122			5		67	5984692.001	Cable Control Panel	1	-	-	-	-	-			
123		4	5		60	5984693.001	Cable Printhead	1	-	-	-	-	-			
124			5		81	5984699.001	PCB Coupling	1	-	-	-	-	-			
125	3				14	5984700.001	Ventilator	1	-	-	-	-	-			

PU Package unit

Notes

B MACH xS/...B

C MACH xS/...C

P MACH xS/...P

1 MACH 4S/300x

2 MACH 4S/600x

3 MACH 4.3S/200x

4 MACH 4.3S/300x

SPR Recommendation

A - wearing parts and accessories

B - recommended spare parts for quick repair

C - recommended spare parts for distributors

D - recommended spare parts for central stores

6 Packaging/Accessories

9

Pos.	Figure/Page				No.	Part No.	Description	PU	SPR					Notes	Serial No.	
															from	to
126					Z	5550611.001	Power Cable Type E+F	1	-	-	-	-				
127					Z	5901655.001	Cable USB	1	-	-	-	-				
128					Z	9109299.001	Packaging	1	-	-	-	-				

PU Package unit

SPR Recommendation

A - wearing parts and accessories

B - recommended spare parts for quick repair

C - recommended spare parts for distributors

D - recommended spare parts for central stores

Notes

B MACH xS/...B

C MACH xS/...C

P MACH xS/...P

1 MACH 4S/300x

2 MACH 4S/600x

3 MACH 4.3S/200x

4 MACH 4.3S/300x